
BEST AVAILABLE COPY









Figure 1a: Correct attachment of tubing



2/18

Figure 1d: Incorrect attachment of tubing

AutoSet ®


AutoSet ®

M

M

H

Figure 1c: Incorrect attachment of tubing






Figure 2: CPAP apparatus




Figure 3a: High motor speed (ω) operation




Figure 3b: Low motor speed (w) operation




Figure 4: Fault diagnosis implemented in overall software processes




Figure 5: Pressure transducer fault regions




Figure 6: Detect Pressure Transducer Stuck Low




Figure 7: Detect Pressure Transducer Stuck High




Figure 8: Detect Flow Transducer Stuck Low




Figure 9: Detect Flow Transducer Stuck High

1




Figure 10: Detect Snore Transducer Stuck Low






Figure 11: Detect Snore Transducer Stuck High





Ĺ




Figure 14: Detect Stalled Motor




Figure 15: Detect Restricted Motor




Figure 16: Software fault






Figure 17: Software fault detection processes